Monitors

DisplayPort acts as plug&play (pnp) devices, so when display is powered off, the device will disappear. This will cause issues in multi-monitor and MST (DP Daisy-Chain) configurations.

Due to the device disappearing and reappearing, the display ID will change and settings like rotations and positions will not point to the correct display any longer.

Options:

- Disable DCC/CI in the monitor settings. This will disable bidirectional communication between the monitor and the pc.
- Enabling DisplayPort 1.2 settings in monitor may help (required for MST anyway)
- Disabling screensaver/power saving options to switch off the monitor can act as a workaround

These linux commands to turn monitors off and on in case they do not come back from sleep:

```
env DISPLAY=:0 xset dpms force off
env DISPLAY=:0 xset dpms force on
```

From:
http://wuff.dyndns.org/ - **Wulf's Various Things**

Permanent link:
http://wuff.dyndns.org/doku.php?id=howto:monitors&rev=1755380981

Last update: **2025/08/16 22:49**