

# Screw conversion

## Screw Size Conversion Chart

Handy chart for converting metric screw sizes to imperial.

Metric sizes listed as M3/M4 etc where the first number is the diameter of the screw, the second is the length.

<b>Metric Size mm</b>	<b>Approx. Inch Equivalent</b>
3.0 x 12	4 x 1/2
3.0 x 20	4 x 3/4
3.0 x 25	4 x 1
3.5 x 12	6 x 1/2
3.5 x 16	6 x 5/8
3.5 x 20	6 x 3/4
3.5 x 25	6 x 1
3.5 x 30	6 x 1 1/4
4.0 x 20	8 x 3/4
4.0 x 25	8 x 1
4.0 x 30	8 x 1 1/4
4.0 x 40	8 x 1 1/2
4.0 x 45	8 x 1 3/4
4.0 x 50	8 x 2
4.0 x 60	8 x 2 1/2
4.0 x 70	8 x 2 3/4
5.0 x 30	10 x 1 1/4
5.0 x 40	10 x 1 1/2
5.0 x 50	10 x 2
5.0 x 60	10 x 2 1/2
5.0 x 70	10 x 2 3/4
5.0 x 80	10 x 3
5.0 x 90	10 x 3 1/2
5.0 x 100	10 x 4
6.0 x 50	12 x 2
6.0 x 60	12 x 2 1/2
6.0 x 70	12 x 2 3/4
6.0 x 80	12 x 3
6.0 x 90	12 x 3 1/2
6.0 x 100	12 x 4

From:

<http://wuff.dyndns.org/> - **Wulf's Various Things**

Permanent link:

<http://wuff.dyndns.org/doku.php?id=3dprinter:screw-conversion>

Last update: **2023/05/29 11:55**

